



**US Army Corps  
of Engineers®**



## **Limited Visual Dam Safety Inspections**

**OA00045**

**Helemano 16 Reservoir**

**Oahu, Hawaii**

**Prepared by:**

**U.S. ARMY CORPS OF ENGINEERS  
HONOLULU DISTRICT**

**STATE OF HAWAII  
DEPARTMENT OF LAND AND NATURAL RESOURCES**

**May 2006**

Limited Visual Dam Safety Inspection Conducted on: 3 April 2006

**I. Purpose:**

Due to disaster occurrences of periodic heavy rains and flooding, which has caused extensive damage to property and loss of lives, the Governor has issued a State of Emergency Proclamation extending from February 20, 2006 to April 9, 2006. In light of the tragic failure of the Kaloko dam on Kauai and the continued forecast of heavy rains, emergency inspections of all regulated dams in all counties are being undertaken.

These inspections are for the purpose of determining if any of the regulated dams and reservoirs in the City and County of Honolulu, Maui County or Hawaii County, are suspect for immediate concern to the downstream area under the prolonged conditions of heavy rain showers.

**II. Authority**

Inspections were authorized under the Hawaii Dam Safety Act of 1987, Chapter 179D "Dams and Reservoirs" of Hawaii Revised Statutes, and Title 13, Subtitle 7, Chapter 190, "Dams and Reservoirs" of the Hawaii Administrative Rules.

These inspections were conducted under joint agreements of the U.S. Army Corps of Engineers (ACE), the U.S. Department of Agriculture Natural Resources Conservation Service (NRCS), and the State of Hawaii. The Memorandum of Agreement with the U.S. Army Corps of Engineers is entered into pursuant to 10 U.S.C. § 3036(d)(2), and the Intergovernmental Cooperation Act (31 U.S.C. §6505), and established via support agreement number DL-06-01.

**III. Scope**

Visual inspection was performed on parts of the embankment and appurtenant works readily available and visible for inspection by the inspection team at the time of the inspection. Such parts and appurtenant works included the upstream slope, crest, downstream slope, abutments and toes, outlet works, and spillway.

On the date of this limited visual inspection, there may or may not have appeared to be any immediate threat to the safety of the dam, however no assurance can be made regarding the dam's condition after this date. Subsequent adverse weather and other factors may affect the dam's condition.

**IV. Limitations of Findings and Recommendations**

The inspection is based only on visible features/areas of the dam on the day of inspection. The inspection does not entail detailed stability, hydrologic, hydraulic, or seismic investigations. This inspection is not a formal phase I or phase II dam safety inspection and does not include a review or evaluation from each specialist of an inspection team, such as a geologists, civil, geotechnical, structural, or hydraulics engineer. The owner should verify the findings of this report and take corrective actions. The owner may submit to the State alternative corrective actions that are certified by a licensed professional engineer in the State of Hawaii experienced in the design and construction of dams. This inspection does not relieve the owner/operator from their responsibility to conduct routine inspections, maintenance, repairs, modifications, monitoring, documentation, and/or investigative studies.

**Dam ID: HI00045**

**Name: Helemano 16 Reservoir**

**V. Inspection Team**

Organization

State of Hawaii, Dept. of Land and Natural Resources  
National Resource Conservation Service  
U.S. Army Corps of Engineers

Name

Carty Chang  
Mike Hayama  
Ray Kong

**VI. Owner's Representatives Present**

Mr. Gary Parcellus, representative of Dole Foods, Inc.

**VII. Summary Report Team**

Organization

U.S. Army Corps of Engineers  
  
State of Hawaii, Dept. of Land and Natural Resources

Name

Mr. Derek Chow  
Mr. Joseph Koester  
Ms. Denise Manuel  
Mr. Edwin Matsuda

**VIII. Dam Type**

The dam is an earthen embankment.

**IX. Dam Classification**

The current hazard classification of this dam is: Unclassified

Based on available data, this classification is believed to still be applicable.

Hazard Potential Classification based on the following:

Category	Loss of Life	Economic Loss
Low	None Expected	Minimal (undeveloped to occasional structures or agriculture)
Significant	Few (No Urban development and no more than a small number of inhabitable structures)	Appreciable (Notable agriculture, industry or structures)
High	More than a few	Extensive community, industry or agriculture.

Based on inventoried storage and height data, the size classification of the dam is: Small

Size Classification based on the following:

Category	Storage (Acre-Feet)	Height (feet)
Small	< 1000	< 40
Intermediate	> 1000 and < 50,000	> 40 and < 100
Large	> 50,000	> 100

**X. Summary of Inspection:**

Condition Rating Criteria: The conditional terms in this report are used to generally described the conditions below. Inspections, monitoring, and additional investigations are considered to be incidental to all condition ratings.

Satisfactory	Expected to fulfill intended function.
Fair	Expected to fulfill intended function, but maintenance is recommended.
Poor	May not fulfill intended function; maintenance or repairs are necessary.
Unsatisfactory	Is not expected to fulfill intended function; repair, replacement, or modification is necessary.
Unknown	Not visible, not accessible, not inspected, or unable to determine the condition rating based on the observation taken.

**A. General appearance:**

Some of the reservoir and dam features were not easily recognizable due to vegetation. There were no signs of any recent modifications. The reservoir appeared to have a small surface drainage area. Based on staff personnel, this reservoir has no history of incidents.

**Findings and Corrective Actions:**

- a. The Owner shall maintain documentations including improvements, modifications, Operations and Maintenance Manuals and routine inspection logs for this dam facility.
- b. An EAP is recommended for all dams regardless of hazard class. Submit EAP if developed for the facility.
- c. Submit narrative and additional information detailing known improvements, modifications, and/or alterations at the dam site, unless covered by approved dam permit.
- d. Routine inspection logs were not inspected.
- e. Dam owners shall provide for routine inspection of the dam.
- f. The dam did not appear to be maintained on a regular basis.
- g. Access to site appears to be satisfactory.
- h. Provide a detailed narrative of the any recalled incident, responses taken, and any damages incurred. Dam owners are required to promptly advise the department of any sudden or unprecedented flood or unusual or alarming circumstance or occurrences which may adversely affect the dam or reservoir.
- i. Submit current Operations and Maintenance Manual or Procedures for this dam / reservoir facility.
- j. Submit Site or Facility Map of this Dam which identifies the location of major features including outlet works controls and conduits.
- k. Emergency Alarms / Monitors. There were no alarms or monitors observed on this reservoir.



- I. Power / Communication. There were no communication systems observed on this reservoir.

**B. Access / Security:**

Access to the dam was accomplished via a County roadway.

A four wheel drive vehicle is not required except maybe during severe weather conditions.

Security issue. Access to the dam is via gates.

**C. Inflow Works:**

The inflow works were not observed. However according to staff personnel, there is one inlet feeding the reservoir. This is via a culvert.

Findings and Corrective Actions:

- a. The intake works were not inspected.
- b. The intake works were not tested.

**D. Reservoir**

The reservoir level during the inspection was approximately 8-feet below the crest elevation. According to staff personnel, the reservoir has not been used for years.

Findings and Corrective Actions:

- a. The reservoir was inspected only along the vicinity of the dam. Other areas were not visible due to heavy vegetation.
- b. The reservoir appeared to be in satisfactory condition, no corrective actions are required at this time.
- c. A staff gage was not observed at the reservoir. Provide some method of quantifying the water level within the reservoir.

**E. Upstream Slope (Fair/Poor)**

The upstream slope appeared to be at a 1V:1H (Vertical/Horizontal) slope.

There was no slope protection observed.

Erosions were not observed, the slope was not entirely visible.

Cracks were not observed, the slope was not entirely visible.

Sinkholes were not observed, the slope was not entirely visible.

The upstream slope was not entirely visible due to heavy woody and grass vegetation.

Findings and Corrective Actions:

- a. The upstream slope was not fully inspected due to heavy vegetation.
- b. The upstream slope appeared to be in fair to poor condition and requires corrective action.
- c. The upstream slope was not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.

**F. Crest: (Satisfactory)**

The dam crest was approximately 30-feet wide

There was a dirt access road on top of the crest.

Minor erosion was observed, limited primarily to tire ruts and some small gullies from surface drainage flowing down the downstream slope.

Vegetation was observed on the edges of the crest. These were primarily tall grass.

Findings and Corrective Actions:

- a. The dam crest appeared to be in satisfactory condition, no corrective actions are required at this time.

**G. Downstream Slope: (Fair)**

The downstream slope was in fair condition and not visible for the most part due to heavy vegetation. The slope was very steep, around a 1V to 1H slope or steeper.

There was no access to the downstream slope, or roadway along the downstream toe. There was no slope protection observed on the downstream slope.

Erosion was not observed on the downstream slope, however the slope was not entirely visible. Cracks were observed perpendicular to crest.

Sinkholes were not observed on the downstream slope, however the slope was not entirely visible.

Vegetation was observed on the downstream slope. The majority of the vegetation was bushes with some woody trees.

Seepage was not observed on the downstream toe, however the toe area was not visible.

Findings and Corrective Actions:

- a. The downstream slope appeared to be in fair condition and requires evaluation.
- b. Slope protection needs maintenance or repair. Description: Downstream slope ½:1 should be evaluated.
- c. A crack was observed on the slope, which requires further investigation to determine the underlining cause. Monitor the area and / or repair as required.
- d. The down stream slope was not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.
- e. Tree(s) were observed on the downstream slope. Trees have been identified as the probably cause of piping failures, and can possibly cause severe damage to the embankment if they are uprooted during a high winds. Corrective action is required to remove the tree hazards from the dam. Acceptable remedies include removal of the tree and its root structure down to a 2" diameter and reconstructing the damaged embankment section. All repair work shall be accomplished as per the requirements of licensed geotechnical or structural engineer. Routinely monitor the damaged area for signs of settlement and seepage.
- f. The slope was very steep, around a 1 to 1 slope, further study is required to verify slope stability.

**H. Abutments / Toe: (Unknown)**

The abutments and toe were not entirely visible or identifiable due to heavy vegetative growth.

Erosion along the abutment or toe was not visible.

Cracks in either direction were not observed, however the abutment and toe was not entirely visible.

There was heavy vegetation along the abutments and toe locations.

Findings and Corrective Actions:

- a. The abutments/toe were not inspected. Not accessible.
- b. The abutments/toe appeared to be in fair to poor condition and requires corrective action.
- c. The abutment/toe area was not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.
- d. Tree(s) were observed along the abutment/toe. Trees have been identified as the probably cause of piping failures, and can possibly cause severe damage to the embankment if they are uprooted during a high winds. Corrective action is required to remove the tree hazards from the dam. Acceptable remedies include removal of the tree and its root structure down to a 2" diameter and reconstructing the damaged embankment section. All repair work shall be accomplished as per the requirements of licensed geotechnical or structural engineer. Routinely monitor the damaged area for signs of settlement and seepage.

**I. Outlet Works: (Unknown)**

No access was observed so the outlet works was not inspected or tested.

The heavy vegetation should be removed and maintained low to enable easy visual inspection. It has not been used for years according to the staff personnel.

Findings and Corrective Actions:

- a. The outlet works were not inspected.
- b. The outlet works were not tested.
- c. The outlet works appeared to be in fair to poor condition and requires corrective action.
- d. Operability of outlet works should be verified.

**J. Spillway: (Fair/Poor)**

This spillway consisted of a concrete lined channel adjacent to the right abutment.

The rough dimensions were 12-feet wide by 8-feet deep.

The spillway approach had tall grass growing in it.

Erosion observed near the spillway.

There was heavy vegetation along the downstream channel.

Further investigations should be conducted to conclude the capacity of the spillway.

Findings and Corrective Actions:

- a. The Spillway appeared to be in fair to poor condition and requires corrective action.

- b. Slope protection needs maintenance or repair. Description: Provide protection against erosion observed.
- c. The spillway approach was partially blocked with vegetation. Clear approach.
- d. Severe scour erosion was observed which requires maintenance and/or repair. Description: Erosion observed at downstream end of the lined spillway.
- e. Unclear if spillway is adequately sized. Spillway should pass the probable maximum flood. Verify spillway capacity and take corrective action as required.

**K. Down Stream Channel: (Unknown)**

The down stream channel was not investigated.

Findings and Corrective Actions:

- a. The downstream channel was not inspected due to inaccessibility.

**XI. Additional Comments:**

Original field inspection notes were scanned and are attached to this summary report. Included are several photos from the site visit to detail important features of the project, captioned to be self-explanatory.

Per e-mail dated 5/12/06, 3:47 pm from Ray Kong, USACE

Please describe vehicle access to site: **Standard car okay.**

Please describe access during rains: **Recommend 4-wheel drive.**

Please describe access when spillway is flowing:

**Depends on weather, standard car usually, 4-wheel during heavy rains.**

Reservoir: Please indicate corrective action.

**No staff gage found, this is therefore an action item for the owner to provide. This reservoir is not being used and the owner may want to breach it.**

Intake Works: **Not inspected.**

Downstream Slope:

Please indicate if the downstream slope is 1V on 1H or 1V on 2H slope. There are two different slope dimensions, one on the typical and the other in the corrective action.

**Appears to be 1V on 1H but could have areas steeper. In any case, the slope stability should be evaluated.**

Comments:

**No immediate threat observed on the day of inspection. All areas not inspected due to heavy vegetation and no accessibility should be made accessible (vegetation removed) for a re-inspection by qualified personnel.**

## PHOTOGRAPHS

**Dam ID: HI00045**

**Name: Helemano 16 Reservoir**



View of reservoir



View of upstream slope



**Dam ID: HI00045**

**Name: Helemano 16 Reservoir**





**Dam ID: HI00045**

**Name: Helemano 16 Reservoir**



Another view of the downstream slope



Another view of the downstream slope



**Dam ID: HI00045**

**Name: Helemano 16 Reservoir**



View of downstream slope showing trees and heavy vegetation



View of the spillway looking upstream




**Dam ID: HI00045**

**Name: Helemano 16 Reservoir**



View of spillway looking upstream; notice erosion where lining ends



View of outlet works; has not been used for years

## **FIELD INSPECTION SHEETS**

Dam ID: OA-0045  
HELEMANO 16 RESERVOIR

Vulnerability Index:  
Extreme High Moderate Low  
1 2 3 4

Inspection No: \_\_\_\_\_  
Date: 3 April 2006

STATE OF HAWAII - DLNR  
DAM SAFETY INSPECTION SHEET

Inspection Type: Visual Dam Safety Inspection

Persons Present

Affiliation

Phone Number

<u>Ray Kong</u>	<u>US Army Corps of Engineers</u>	
<u>Cathy Chang</u>	<u>DLNR</u>	
<u>Mike Hayama</u>	<u>NRCS</u>	
<u>Gary Parcellus</u>	<u>Dole</u>	

Weather Condition: ☐ Rain previous day ☐ Rainy ☐ Drizzle / Mist ☐ Cloudy/Overcast ☐ Partly Cloudy ☒ Sunny ☐ Dry

Comments: \_\_\_\_\_

1. General: (Information currently on file, update as required)

Dam/Res. Name	<u>HELEMANO 16 RESERVOIR</u>		
Owner	<u>Dole Food Company Hawaii</u> (C005)		
Owner Contact	<u>Mr. Gary Paracuellas</u>	Owner Ph.	_____
Lessee	_____	Lessee Ph.	_____
O & M Contractor	_____	O & M Ph.	_____
Nearest Town	<u>KEMOO CAMP 4</u>	Latitude	<u>21.5583° (decimal)</u>
County	<u>HONOLULU</u>	Longitude	<u>159.07° (decimal)</u>
Tax Map Key(s)	<u>(1)6-4-003:001</u>		

Dam Status	<u>A:</u>	Hazard Potential	<u>U:</u>	Dam Size	_____
Year Completed	<u>1955</u>	Dam Length	<u>300</u> ft.	Dam Height	<u>17</u> ft.
Normal Storage	<u>55</u> ac.ft.	Max. Storage	<u>65</u> ac.ft.	Max. Surface Area	<u>0</u> ac.
Drainage Area	<u>0</u> mi.	Spillway Type	_____	Max. Spillway Q	<u>0</u> cfs

Owner owns land under dam facility: \_\_\_\_\_

Emergency Action Plan on file with the Department: NO

Reports on file with the Department: None on file.

Dam ID: OA-0045  
HELEMANO 16 RESERVOIR

Inspection No: \_\_\_\_\_  
Date: 04/03/06

2. Questions for Owner's Rep.:

	Yes	No	Unknown	Comments
Construction Plans Available	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Site / Facility Map	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Operation & Maintenance Manual	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Emergency Action Plan	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Modifications / Improvements	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Conduct Routine Inspections	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Conduct Routine Maintenance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	
Vehicle access to site	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Not accessible <input type="checkbox"/> With Standard car <input type="checkbox"/> Requires 4-Wheel Drive
Access during heavy rains	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Not accessible <input type="checkbox"/> With Standard car <input type="checkbox"/> Requires 4-Wheel Drive
Access when spillway is flowing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Not accessible <input type="checkbox"/> With Standard car <input type="checkbox"/> Requires 4-Wheel Drive
Other Studies Conducted	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Phase I <input type="checkbox"/> Phase II <input type="checkbox"/> Hydraulics <input type="checkbox"/> Stability <input type="checkbox"/> Hazard <input type="checkbox"/> Seismic <input type="checkbox"/> Other: _____
Incident History	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Breached <input type="checkbox"/> Overtop <input type="checkbox"/> Slide <input type="checkbox"/> Down stream Flooding <input type="checkbox"/> Other: _____
Reservoir's Current Use	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/> Sediment <input type="checkbox"/> Irrigation <input type="checkbox"/> Recreation <input type="checkbox"/> Flood Control <input type="checkbox"/> Drinking Water <input type="checkbox"/> Power Generation <input type="checkbox"/> Other: <u>Not currently being used.</u> <u>when in use for irrigation</u>

Findings and Corrective Actions:

- ☒ a. The Owner shall maintain documentations including Construction plans, specifications, improvements, modifications, Operations and Maintenance Manuals and routine inspection logs for this dam facility. 4/23/06 a
- ☐ b. An Emergency Action Plan (EAP) is on file with the department, submit any updates as applicable.
- ☐ c. An EAP is required for High Hazard Dams. Submit an updated EAP for this facility.
- ☒ d. An EAP is recommended for all dams regardless of hazard class. Submit EAP if developed for the facility. 4/23/06 a
- ☐ e. Submit narrative and additional information detailing the improvements, modifications, and/or alterations at the dam site, unless covered by approved dam permit.
- ☒ f. Routine inspection logs were not inspected.
- ☒ g. Dam owners shall provide for routine inspection of the dam.
- ☐ h. The dam did not appear to be maintained on a regular basis.
- ☒ i. Access to site appears to be satisfactory.
- ☐ j. There is no vehicular access to the dam site. Operational and emergency plans need to reflect this deficiency or access provided.
- ☐ k. Access to dam is questionable during severe weather conditions and/or spillway overflows. Operational plans and emergency plans need to reflect this deficiency or access provided.
- ☐ l. Provide a detailed narrative of the incident, responses taken, and any damages incurred. Dam owners are required to promptly advise the department of any sudden or unprecedented flood or unusual or alarming circumstance or occurrences which may adversely affect the dam or reservoir.
- ☒ m. Submit current Operations and Maintenance Manual or Procedures for this dam / reservoir facility. 4/23/06 a
- ☒ n. Submit Site or Facility Map of this Dam which identifies the location of major features including outlet works controls and conduits. 4/23/06 a
- ☐ o. \_\_\_\_\_

Additional Requirements:

The following investigative study(s) are:

Required	Recommended	
<input type="checkbox"/>	<input type="checkbox"/>	Phase I Study
<input type="checkbox"/>	<input type="checkbox"/>	Phase II Study (Including <input type="checkbox"/> Seepage <input type="checkbox"/> Hydrology/Hydraulics <input type="checkbox"/> EAP)
<input type="checkbox"/>	<input type="checkbox"/>	Hydrology and Hydraulics (including Probable Maximum Flood and spillway capacity)
<input type="checkbox"/>	<input type="checkbox"/>	Stability Analysis
<input type="checkbox"/>	<input type="checkbox"/>	Seismic Analysis
<input type="checkbox"/>	<input type="checkbox"/>	Hazard Classification
<input type="checkbox"/>	<input type="checkbox"/>	Other: _____



Dam ID: OA-0045  
HELEMANO 16 RESERVOIR

Inspection No: \_\_\_\_\_  
Date: 04/03/06

**Physical Dam Features:** (Check All Applicable. Provide description of Items Observed and/or Take Photos. Indicate photo # in description.)

**3. Reservoir:**

Level during inspection \_\_\_\_\_ ft per \_\_\_\_\_ (gage / other) Approx 8' below crest  
Normal Operating Level/Range \_\_\_\_\_ ft per \_\_\_\_\_ (gage / other) unknown same  
Description: \_\_\_\_\_  
Typical Operation ☐ Spillway always flowing ☐ Kept within normal range ☐ Kept Empty ☐ Drained Daily ☐ Only filled by Storms  
☒ Other: Not in use  
Sinkhole in Res.: ☐ # Observed: \_\_\_\_\_ Size: \_\_\_\_\_ by \_\_\_\_\_ in. Deep ☐ Not Visible ☒ None Observed  
Description: \_\_\_\_\_  
Staff Gage: Description: none

**Findings:**

- ☐ a. The reservoir was not inspected.  
☒ b. The reservoir appeared to be in satisfactory condition, no corrective actions are required at this time.  
☐ c. The reservoir appeared to be in fair to poor condition and requires corrective action.  
☐ d. The reservoir appeared to be in unsatisfactory condition, urgent corrective action is required.

**Corrective Actions:**

- ☐ e. The staff gage needs maintenance and/or repair. Description: \_\_\_\_\_  
☐ f. A staff gage was not observed at the reservoir. Provide some method of quantifying the water level within the reservoir.  
☐ g. A sinkhole was observed in the upstream reservoir. Conduct additional investigations and monitoring to identify the cause, risk and appropriate action.  
☐ h. \_\_\_\_\_

**4. Intake Works Description:**

☒ Number of Intakes 1  
☐ Intake Culvert / Pipe  
Size: \_\_\_\_\_ in. ☐ DIP ☐ Corrugated Metal ☐ PVC ☐ HDPE ☐ Concrete ☐ Other \_\_\_\_\_  
Control: ☐ Gate ☐ Valve ☐ Flow can either be Shut off or Bypassed  
From: ☐ Stream Diversion ☐ Pump ☐ Reservoir ☒ Other currently closed - not sure what type  
☐ Ditch / Flume  
Dimension: \_\_\_\_\_ (Size x Depth) Shape \_\_\_\_\_  
Surface: ☐ Dirt ☐ Wood ☐ Concrete ☐ Lined w/ \_\_\_\_\_  
Control: ☐ Gate ☐ Valve ☐ Flow can either be Shut off or Bypassed  
From: ☐ Stream Diversion ☐ Pump ☐ Reservoir ☐ Other \_\_\_\_\_

**Findings:**

- ☒ a. The intake works were not inspected.  
☐ b. The intake works were not tested.  
☐ c. The intake works appeared to be in satisfactory condition, no corrective actions are required at this time.  
☐ d. The intake works appeared to be in fair to poor condition and requires corrective action.  
☐ e. The intake works appeared to be in unsatisfactory condition, urgent corrective action is required.

**Corrective Actions:**

- ☐ f. The intake works needs maintenance and/or repair. Description: \_\_\_\_\_  
☐ g. \_\_\_\_\_

Dam ID: OA-0045  
HELEMANO 16 RESERVOIR

Inspection No: \_\_\_\_\_  
Date: 04/03/06

**5. Upstream Slope:**

(Typical Slope  $\pm$  1V : 1H)

Slope Protection: ☒ None ☐ Dumped Rock ☐ Fitted Rip Rap ☐ Grouted Rip Rap ☐ Liner \_\_\_\_\_ ☐ Other: \_\_\_\_\_

☐ Defect in Protection: Description: \_\_\_\_\_

Erosion: ☒ Loose soil w/ little vegetation ☒ Rut (<6") ☐ Gully (>6" deep) ☐ Not Visible ☐ None Observed

Description: \_\_\_\_\_

Cracks: ☐ Parallel with crest ☒ Perpendicular to crest ☐ Slide visible ☐ Not Visible ☐ None Observed

Description: \_\_\_\_\_

Sinkholes: ☐ # Observed: \_\_\_\_\_ Size: \_\_\_\_\_ and \_\_\_\_\_ Depth ☐ Not Visible ☒ None Observed

Description: \_\_\_\_\_

Vegetation: ☐ None ☒ Low Ground Cover ☐ Bushes or Tall Grass ☐ Trees # \_\_\_\_\_ ☐ <6" ☐ >6" & <20" ☐ >20"

Description: Also dead tree roots

**Findings:**

- ☐ a. The upstream slope was not inspected.
- ☒ b. The upstream slope appeared to be in satisfactory condition, no corrective actions are required at this time.
- ☐ c. The upstream slope appeared to be in fair to poor condition and requires corrective action.
- ☐ d. The upstream slope appeared to be in unsatisfactory condition and not expected to fulfill its intended function. Urgent corrective action is required.

**Corrective Actions:**

- ☐ e. Slope protection needs maintenance or repair. Description: \_\_\_\_\_
- ☐ f. Rut and/or Gully erosion was observed on the slope, which requires maintenance and/or repair. Description: \_\_\_\_\_
- ☐ g. A crack was observed on the slope, which requires further investigation to determine the underlining cause. Monitor the area and/or repair as required.
- ☐ h. A sinkhole was observed on the slope, which requires further investigation to determine the underlining cause. Repair and monitor the area.
- ☐ i. The upstream slope was not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.
- ☐ j. Tree(s) were observed on the dam embankment. Trees have been identified as the probably cause of piping failures, and can possibly cause sever damage to the embankment if they are uprooted during a high winds. Corrective action is required to remove the tree hazards from the dam. Acceptable remedies include removal of the tree and its root structure down to a 2" diameter and reconstructing the damaged embankment section. All repair work shall be accomplished as per the requirements of licensed geotechnical or structural engineer. Routinely monitor the damaged area for signs of settlement and seepage.
- ☐ k. \_\_\_\_\_

Dam ID: OA-0045  
HELEMANO 16 RESERVOIR

Inspection No: \_\_\_\_\_

Date: 04/03/04

**6. Crest:**

Approximate Crest Width: 30'

Access: ☐ None ☐ Walking Path ☒ Roadway, Surface / Width / Usage: Dirt / 30' / Vehicle, pedestrian  
Erosion: ☐ Loose soil w/ little vegetation ☐ Rut (<6") ☐ Gully (>6" deep) ☐ Not Visible ☒ None Observed Access

Description: \_\_\_\_\_

Cracks: ☐ Parallel with crest ☐ Perpendicular to crest ☐ Slide visible ☐ Not Visible ☒ None Observed

Description: \_\_\_\_\_

Sinkholes: ☐ \_\_\_\_\_ in. Wide x \_\_\_\_\_ in. Long x \_\_\_\_\_ in. Deep ☐ Not Visible ☒ None Observed

Description: \_\_\_\_\_

Vegetation: ☒ None ☐ Low Ground Cover ☐ Bushes or Tall Grass ☐ Trees # \_\_\_\_\_ ☐ <6" ☐ >6" & <20" ☐ >20"

Description: \_\_\_\_\_

**Findings:**

- ☐ a. The dam crest was not inspected.  
☒ b. The dam crest appeared to be in satisfactory condition, no corrective actions are required at this time.  
☐ c. The dam crest appeared to be in fair to poor condition and requires corrective action.  
☐ d. The dam crest appeared to be in unsatisfactory condition and not expected to fulfill its intended function. Urgent corrective action is required.

**Corrective Actions:**

- ☐ e. Access along the crest was satisfactory.  
☐ f. Access along the crest was not possible. Description: \_\_\_\_\_  
☐ g. Rut and/or Gully erosion was observed on the crest, which requires maintenance and/or repair. Description: \_\_\_\_\_  
☐ h. A crack was observed on the crest, which requires further investigation to determine the underlining cause. Monitor the area and/or repair as required.  
☐ i. A sinkhole was observed on the crest, which requires further investigation to determine the underlining cause. Repair and monitor the area.  
☐ j. Portions of the crest were not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.  
☐ k. Tree(s) were observed along the dam crest. Trees have been identified as the probably cause of piping failures, and can possibly cause sever damage to the embankment if they are uprooted during a high winds. Corrective action is required to remove the tree hazards from the dam. Acceptable remedies include removal of the tree and its root structure down to a 2" diameter and reconstructing the damaged embankment section. All repair work shall be accomplished as per the requirements of licensed geotechnical or structural engineer. Routinely monitor the damaged area for signs of settlement and seepage.  
☐ l. \_\_\_\_\_



Dam ID: OA-0045  
HELEMANO 16 RESERVOIR

Inspection No: \_\_\_\_\_

Date: 04/03/06

(Typical Slope  $\pm \frac{1}{2} : 1$ )

### 7. Downstream Slope:

Access: ☐ lower roadway along toe ☐ roadway to outlet works ☐ walkway to outlet works ☒ None Observed

Slope Protection: ☒ None ☐ Dumped Rock ☐ Rip Rap ☐ Grouted Rip Rap ☐ Concrete

Erosion: ☒ Loose soil w/ little vegetation ☐ Rut (<6") ☒ Gully (>6" deep) ☐ Not Visible ☐ None Observed

Description: \_\_\_\_\_

Cracks: ☐ Parallel with crest ☒ Perpendicular to crest ☐ Slide visible ☐ Not Visible ☐ None Observed

Description: \_\_\_\_\_

Sinkholes: ☐ \_\_\_\_\_ in. Wide x \_\_\_\_\_ in. Long x \_\_\_\_\_ in. Deep ☐ Not Visible ☒ None Observed

Description: \_\_\_\_\_

Vegetation: ☐ None ☒ Low Ground Cover ☐ Bushes or Tall Grass ☒ Trees # 2 large ☐ <6" ☒ >6" & <20" ☐ >20"

Description: Numerous Hole Koa 2" diameter trunk size

Seepage: Seep Spot Number 1

☐ Green Vegetation ☐ Wet or Muddy Ground ☐ Ponding Water ☐ Not Visible ☒ None Observed

☐ Flowing, Description: \_\_\_\_\_

Water Clarity: ☐ Clear ☐ Some particles ☐ Muddy ☐ Other: \_\_\_\_\_

Description: \_\_\_\_\_

Seep Spot Number 2

☐ Green Vegetation ☐ Wet or Muddy Ground ☐ Ponding Water ☐ Not Visible ☐ None Observed

☐ Flowing, Description: \_\_\_\_\_

Water Clarity: ☐ Clear ☐ Some particles ☐ Muddy ☐ Other: \_\_\_\_\_

Description: \_\_\_\_\_

### Findings:

- ☐ a. The downstream slope was not inspected.
- ☐ b. The downstream slope appeared to be in satisfactory condition, no corrective actions are required at this time.
- ☒ c. The downstream slope appeared to be in fair to poor condition and requires corrective action. Evaluation
- ☐ d. The downstream slope appeared to be in unsatisfactory condition and not expected to fulfill its intended function. Urgent corrective action is required.

### Corrective Actions:

- ☒ e. Slope protection needs maintenance or repair. Description: Downstream slope 1/2:1 should be evaluated
- ☐ f. Rut and/or Gully erosion was observed on the slope, which requires maintenance and/or repair.  
Description: \_\_\_\_\_
- ☐ g. A crack was observed on the slope, which requires further investigation to determine the underlining cause. Monitor the area and/or repair as required.
- ☐ h. A sinkhole was observed on the slope, which requires further investigation to determine the underlining cause. Repair and monitor the area.
- ☐ i. The down stream slope was not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.
- ☒ g. Tree(s) were observed on the downstream slope. Trees have been identified as the probably cause of piping failures, and can possibly cause sever damage to the embankment if they are uprooted during a high winds. Corrective action is required to remove the tree hazards from the dam. Acceptable remedies include removal of the tree and its root structure down to a 2" diameter and reconstructing the damaged embankment section. All repair work shall be accomplished as per the requirements of licensed geotechnical or structural engineer. Routinely monitor the damaged area for signs of settlement and seepage. 4/13/06
- ☐ h. Seepage/Ponding water was observed. Monitor and conduct further investigation to locate the source of water and extent of any possible hazardous or developing condition.
- ☐ i. Seepage was observed flowing and particles were observed to be removed by the flow. Take immediate action to stop the loss of soil from the embankment. Conduct further investigation to determine the underlining cause and take corrective action. Monitor the area.
- ☒ j. The slope was very steep, around a 1 to 1 slope, further study is required to verify slope stability. 4/13/06
- ☐ k. \_\_\_\_\_

Dam ID: OA-0045  
HELEMANO 16 RESERVOIR

Inspection No: \_\_\_\_\_  
Date: 04/03/06

### 8. Abutments/Toe:

Erosion: ☐ Loose soil w/ little vegetation ☐ Rut (<6") ☐ Gully (>6" deep) ☐ Not Visible ☒ None Observed  
Description: \_\_\_\_\_

Cracks: ☐ Parallel with crest ☐ Perpendicular to crest ☐ Slide visible ☐ Not Visible ☒ None Observed  
Description: \_\_\_\_\_

Vegetation: ☐ None ☒ Low Ground Cover ☐ Bushes or Tall Grass ☐ Trees # \_\_\_\_\_ ☐ <6" ☐ >6" & <20" ☐ >20"  
Description: \_\_\_\_\_

Seepage: Seep Spot Number 1  
☐ Green Vegetation ☐ Wet or Muddy Ground ☐ Ponding Water ☐ Not Visible ☒ None Observed  
☐ Flowing, Description: \_\_\_\_\_  
Water Clarity: ☐ Clear ☐ Some particles ☐ Muddy ☐ Other: \_\_\_\_\_  
Description: \_\_\_\_\_

Seep Spot Number 2  
☐ Green Vegetation ☐ Wet or Muddy Ground ☐ Ponding Water ☐ Not Visible ☐ None Observed  
☐ Flowing, Description: \_\_\_\_\_  
Water Clarity: ☐ Clear ☐ Some particles ☐ Muddy ☐ Other: \_\_\_\_\_  
Description: \_\_\_\_\_

### Findings:

- ☒ a. The abutments/toe were not inspected. *Not Accessible*
- ☒ b. The abutments/toe appeared to be in satisfactory condition, no corrective actions are required at this time.
- ☐ c. The abutments/toe appeared to be in fair to poor condition and requires corrective action.
- ☐ d. The abutments/toe appeared to be in unsatisfactory condition and not expected to fulfill its intended function. Urgent corrective action is required.

### Corrective Actions:

- ☐ e. Slope protection needs maintenance or repair. Description: \_\_\_\_\_
- ☐ f. Rut and/or Gully erosion was observed, which requires maintenance and/or repair.  
Description: \_\_\_\_\_
- ☐ g. A crack was observed along the abutments/near the toe, which requires further investigation to determine the underlining cause. Monitor the area and/or repair as required.
- ☐ h. The abutment/toe area was not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.
- ☐ i. Tree(s) were observed along the abutment/toe. Trees have been identified as the probably cause of piping failures, and can possibly cause sever damage to the embankment if they are uprooted during a high winds. Corrective action is required to remove the tree hazards from the dam. Acceptable remedies include removal of the tree and its root structure down to a 2" diameter and reconstructing the damaged embankment section. All repair work shall be accomplished as per the requirements of licensed geotechnical or structural engineer. Routinely monitor the damaged area for signs of settlement and seepage.
- ☐ j. Seepage/Ponding water was observed. Monitor and conduct further investigation to locate the source of water and extent of any possible hazardous or developing condition.
- ☐ k. Seepage was observed flowing and particles were observed to be removed by the flow. Take immediate action to stop the loss of soil from the embankment. Conduct further investigation to determine the underlining cause and take corrective action. Monitor the area.
- ☐ l. \_\_\_\_\_

Dam ID: OA-0045  
HELEMANO 16 RESERVOIR

Inspection No: \_\_\_\_\_  
Date: 04/03/06

**9. Outlet Works:**

Culvert / Pipe

Type / Size:

Valve Box into pipe (material unknown)

Culvert:

☐ Concrete ☐ Masonry ☐ unlined earth ☐ Other \_\_\_\_\_

Pipe:

☐ DIP ☐ Corrugated Metal ☐ PVC ☐ HDPE ☐ Concrete ☐ Other pipe type / size

Control Type:

☐ Gate ☒ Valve ☐ Other \_\_\_\_\_  
unknown

Location:

☐ Control on Upstream side ☐ Control on Downstream side

Seepage:

☐ Green Vegetation ☐ Wet or Muddy Ground ☐ Ponding Water ☐ Not Visible ☒ None Observed

☐ Flowing, Description: \_\_\_\_\_

Water Clarity: ☐ Clear ☐ Some particles ☐ Muddy ☐ Other: \_\_\_\_\_

Description: \_\_\_\_\_

**Findings:**

- ☐ a. The outlet works were not inspected.
- ☐ b. The outlet works were not tested.
- ☒ c. The outlet works appeared to be in satisfactory condition, no corrective actions are required at this time.
- ☐ d. The outlet works appeared to be in fair to poor condition and requires corrective action.
- ☐ e. The outlet works appeared to be in unsatisfactory condition and not expected to fulfill its intended function. Urgent corrective action is required.

**Corrective Actions:**

- ☐ f. Seepage/Ponding water was observed. Conduct further investigation to locate the source of water and extent of any possible hazardous or developing condition.
- ☐ g. Seepage was observed flowing and particles were observed to be removed by the flow. Take immediate action to stop the loss of soil. Conduct further investigation to determine the underlining cause and take corrective action. Monitor the area. Failures caused by seepage/piping along the outlet conduit are very common and are considered to be a dangerous situation.
- ☐ h. Were not visible due to high grass and bush vegetation. Clear high vegetation and maintain low to enable easy visual inspection.
- ☐ i. \_\_\_\_\_
- ☐ j. \_\_\_\_\_

Dam ID: OA-0045  
HELEMANO 16 RESERVOIR

Inspection No: \_\_\_\_\_  
Date: 04/03/06

### 10. Spillway:

Type: ☐ None ☐ Culvert/Pipe ☒ Channel  
Description: Concrete Box Culvert  
Dimension: 12' x 8' ft. Invert elevation: \_\_\_\_\_ ft. per staff gage  
Slope Protection: ☐ None ☐ Grass ☐ Dumped Rock ☐ Fitted Rip Rap ☐ Grouted Rip Rap ☒ Concrete  
☐ Defect in Protection: Description: \_\_\_\_\_  
Approach: ☒ Clear ☐ High Veg. ☐ Trees ☐ Other: \_\_\_\_\_  
Erosion: ☐ Scour ☐ Gully ☐ Headcut ☒ Not Observed ☐ Other: \_\_\_\_\_  
Description: \_\_\_\_\_  
Vegetation: ☒ None ☐ Low Ground Cover ☐ Bushes or Tall Grass ☐ Trees # \_\_\_\_\_ ☐ <6" ☐ >6" & <20" ☐ >20"  
Description: \_\_\_\_\_

#### Findings:

- ☒ a. The Spillway appeared to be in satisfactory condition, no corrective actions are required at this time.  
☐ b. The Spillway appeared to be in fair to poor condition and requires corrective action.  
☐ c. The Spillway appeared to be in unsatisfactory condition and not expected to fulfill its intended function. Urgent corrective action is required.

#### Corrective Actions:

- ☐ d. Slope protection needs maintenance or repair. Description: \_\_\_\_\_  
☐ e. The spillway approach was blocked. Clear approach.  
☐ f. Severe scour erosion was observed which requires maintenance and/or repair.  
Description: \_\_\_\_\_  
☐ g. A headcut (vertical drop in channel due to erosion) was observed downstream of the spillway. Corrective action is required to prevent this problem from moving upstream.  
☐ h. Trees are unacceptable in the spillway channel and approach. Take corrective action to address the woody vegetation problem and repair the damaged area.  
☐ i. Unclear if spillway is adequately sized. Spillway should pass the probable maximum flood. Verify spillway capacity and take corrective action as required.  
☐ j. \_\_\_\_\_

### 11. Down Stream Channel:

Name: Helemano  
Downstream: ☐ Sump ☐ Open Area ☐ Un-Defined Drainage-way ☐ Defined Drainage-way ☒ Other Helemano  
Items along Stream Bank: ☐ None ☐ Road ☐ Houses ☐ Town ☒ Not Inspected  
Description: \_\_\_\_\_

#### Findings:

- ☒ a. The downstream channel was not inspected. Not Accessible  
☐ b. The downstream channel appeared to be in satisfactory condition, no corrective actions are required at this time.  
☐ c. The downstream channel appeared to be in fair to poor condition and requires corrective action.  
☐ d. The downstream channel appeared to be in unsatisfactory condition and not expected to fulfill its intended function. Urgent corrective action is required.

#### Corrective Actions:

- ☐ e. \_\_\_\_\_

**Dam ID:** OA-0045  
HELEMANO 16 RESERVOIR

Inspection No: \_\_\_\_\_  
Date: 04/03/00

On the date of this limited visual inspection, there appeared to be no immediate threat to the safety of the dam. No assurance can be made regarding the dam's condition after this date. Subsequent adverse weather and other factors may affect the dam's condition.